61714		.*	
ROLL No.			_

TEST BOOKLET No.

56

TEST FOR POST GRADUATE PROGRAMMES

INSTRUMENTATION

Time: 2 Hours

Maximum Marks: 450

INSTRUCTIONS TO CANDIDATES

- 1. You are provided with a Test Booklet and an Optical Mark Reader (OMR) Answer Sheet to mark your responses. Do not soil the Answer Sheet. Read carefully all the instructions given on the Answer Sheet.
- 2. Write your Roll Number in the space provided on the top of this page.
- 3. Also write your Roll Number, Test Code, and Test Subject in the columns provided for the same on the Answer Sheet. Darken the appropriate bubbles with a Ball Point Pen.
- 4. The paper consists of 150 objective type questions. All questions carry equal marks.
- 5. Each question has four alternative responses marked A, B, C and D and you have to darken the bubble fully by a Ball Point Pen corresponding to the correct response as indicated in the example shown on the Answer Sheet.
- 6. Each correct answer carries 3 marks and each wrong answer carries 1 minus mark.
- 7. Space for rough work is provided at the end of this Test Booklet.
- 8. You should return the Answer Sheet to the Invigilator before you leave the examination hall. However, you can retain the Test Booklet.
- 9. Every precaution has been taken to avoid errors in the Test Booklet. In the event of any such unforeseen happenings, the same may be brought to the notice of the Observer/Chief Superintendent in writing. Suitable remedial measures will be taken at the time of evaluation, if necessary.

A A A A A

27

7 (17) 1 (17)

INSTRUMENTATION

1.	A null type of instrument as	compared	to a	deflection	type	instrument
	has					

(A) a higher accuracy

(B) a higher sensitivity

a faster response

(D) All the above

2. In a measurement system, the open loop transfer function is 10 and change by 10 percent. If a closed loop system is adopted, where the feedback system has a transfer function of 100, the change in the output in the case of open loop and closed loop systems are,

(A) $10 \%, 10*10^{-3} \%$ (C) $100\%, 10*10^{-3} \%$

(B) $10 \%, 1*10^{-3} \%$ (D) $100\%, 1*10^{-3} \%$

A measurement system with input x(t) and output y(t) is described by 3. the differential equation $3\frac{dy}{dt} + 5y = 8x$. The static sensitivity of the system is

(A) 0.60

(B) 1.60

1.67

(D) 2.67

4. The volume of a cylinder is computed from measurements of its height (h) and diameter (d). A set of several measurements of height has an average value of 0.2m and a standard deviation of 1%. The average value obtained for the diameter is 0.1m and the standard deviation is 1%. Assuming that the errors in the measurement of height and diameter are uncorrelated, the standard deviation of the compound volume is

(A) 1.00%

(B) 1.73%

(C) 2.23%

(D) 2.41%

2 ¹5. The response of a first-order measurement system to a unit step input is $1-e^{-0.5t}$, where t is in seconds. A ramp of 0.1 units per second is given as the input to this system. The error in the measured value after transients have died down is (A) 0.02 units (B) 0.1 units (C) 0.2 units (D) 1 unit Accuracy of an instrument is defined as 6.

- closeness of the indicated value to the true value (A)
- closeness of the indicated value to the error
- closeness among the indicted values
- None of the above
- 7. The best way to specify accuracy of an instrument is
 - (A) as a percentage of error
 - as a percentage of the true value
 - as a percentage of scale range
 - (D) as point accuracy
- 8. The threshold and resolution are
 - (A) smallest measurable input and input change
 - smallest measurable output and output change
 - smallest measurable input change and input
 - (D) None of the above
- A reading is recorded 23.90°C. The reading has
 - (A) three significant figures
- (B) five significant figures
- (C) four significant figures
- (D) None of the above
- A 0-10 A ammeter has a guaranteed accuracy of 1 percent of full 10. scale deflection. The limiting error while reading 2.5 A is
 - (A) 1%

(B) 2%

(C) 4%

(D) None of the above

		3		
11.	A wattmeter has a full scale of the true value. What would			
	1250W?			
	. *			
	(A) 1225 - 1275W	(B)	1245 - 1255W	
	(C) 1200 - 1300W	(D)	1237 - 1262W	
12.	The voltage of a potentiome	ter is measu	red by a voltmeter l	naving an
12.	input impedance comparat	ole of the	output impedance	of the

- potentiometer, thereby causing an error in the measurement. The error may be called as
 - (A) gross error
 - (B) random error
 - (C) error caused by misuse of instrument
 - (D) error caused by loading effect
- For a Gaussian distribution, the probable error is r. This means that 13.
 - (A) area under the curve between ±r limits is 0.5
 - (B) half of the observed values lie between ±r limits
 - the chances that an additional observation will lie between $\pm r$ limits are 50%
 - All of the above (D)
- 14. If the confidence level is 0.95, then the value lying outside the confidence interval is
 - (A) 1 in 5

(B) 1 in 20

(C) 1 in 100

- (D) 1 in 1000
- A batch of resistors have a mean value of 100.00Ω and a standard \sim deviation of $\sigma = 0.2\Omega$. The probability corresponding to 2σ is 0.9546. The value of odds that randomly selected resistor will lie within $100.00 \pm 0.40\Omega$ is
 - (A) 1 to 1

(B) 2.15 to 1

(C) 21 to 1

(D) 256 to 1

			~		
16.	compo	rmometer with time rature cycling with 60 tput to input are	constant of	f 60s is used to	for measuring ag and ratio of
		63.6 s, 0.847 53.6 s, 0.647	(B) (D)	53.6s, 0.847 None of the al	bove
17.	The tin	ne constant is defined	as		
	(A) (B) (C) (D)	The second co	36.8% of its	initial value	value if initial
18.	Dynam	ic error is			
	(A) (B) (C) (D)	difference between with time and measu difference between the difference between with time All of the above	red value he true value	and measured v	alue
19.	maximu	aperature of a furnace am time constant of a temperature is read w	first order in	strument that ca	n he used so
	(A) (C)	50s 50ms	(B) (D)		
20.	A first of input. T	order system with a the settling time of the	ime constant e system is	of 20 is subjec	ted to a step
	(A) (C)	100s 20s	(B) (D)	60s infinity	

21. A certain system exhibited an overshoot of 16% when subjected to an input of 2u(t), where u(t) is a step input. The damping ratio and decay ratio, respectively, are

(A) (0.8, 0.0810)

(B) (0.5, 0.0256)

(C) (1.0, 0.1626)

(D) (1.1, 0.0089)

22. The following terms used in the context of an instrument are numbered as shown

(1) Accuracy

(2) Sensitivity

(3) Precision

(4) Resolution

Match these with their possible definitions listed below:

P. Repeatability of readings on successive observations

Q. Smallest perceptible change in the output

R. Deviation of the output from the true value

S. Minimum value of the input from the true value

T. Ratio of the change in the instrument reading to the change in the measured variable

(A) 1-P, 2-Q, 3-R, 4-S

(B) 1-S, 2-Q, 3-P, 4-T

(C) 1-R, 2-T, 3-P, 4-Q

(D) 1-T, 2-Q, 3-P, 4-S

23. The calibration data for a pressure compensator of a pump is given below:

Input x	0	1	2	. 3	4	5	6	7	8	9	10
Output y	9.5	8.4	7.8	7.4	6.1	5.4	5.2	4.6	3.2	1.9	1.1

For the given data, the slope of the best-fit line applying the least-squares method is

(A) 0.921

(B) - 0.803

(C) 0.819

(D) - 0.945

- 24. A wire potentiometer of length 11m and resistance $1\Omega/m$ balances a standard cell voltage of 1.018V at a length of 10.18m. If the voltage of the battery supplying the current through the potentiometer is 2.0V, then the value of the series resistance connected to the potentiometer is
 - (A) 9Ω

(B) 90Ω

(C) 900Ω

(D) 990Ω

- 25. The torque in a rotating shaft is measured using strain gauges. The strain gauges must be positioned on the shaft such that the axes of the strain gauges are at
 - (A) 0 with respect to the axis of the shaft
 - (B) 30 with respect to the axis of the shaft
 - (C) 45 with respect to the axis of the shaft
 - (D) 90 with respect to the axis of the shaft
- 26. In a second order system, the damping factor is 0.65 and the natural frequency is 4Hz. If the stiffness of springs is halved, the new values of damping factor and natural frequency are
 - (A) 0.92, 2.83Hz

(B) 0.46, 5.66Hz

(C) 0.92, 5.66Hz

(D) 0.46, 2.83Hz

- 27. The temperature transducers exhibit nonlinear behavior. The order in which they exhibit nonlinearity (highest to lowest) is
 - (A) thermocouples, RTDs, thermistors
 - (B) thermistors, thermocouples, RTDs
 - (C) RTDs, thermocouples, thermistors
 - (D) thermistors, RTDs, thermocouples

28. The output of a strain gauge bridge using two active strain gauges used in Poission's configuration is

(A)
$$\frac{\upsilon G_f \varepsilon e_i}{4}$$
.

(B)
$$\frac{\upsilon G_f \varepsilon e_i}{2}$$

(C)
$$\frac{(1+\upsilon)G_f\varepsilon e_i}{2}$$

(D)
$$\frac{(1+\upsilon)G_f\varepsilon e_i}{4}$$

where, v = Poisson's ratio, $G_f = Gauge factor,$ and e_i = excitation voltage of bridge.

29. For a vertical Venturimeter with acquired water flow, when the measured static pressure difference p₁-p₂, between the inlet and throat is 30kPa, the flow rate is found to be 50 lit/sec; assume that the coefficient of discharge remains the same. When p₁-p₂ =20kPa, the flow rate in lit/sec is

(A) 33.3

(C) 40.8

(D) 54.2

30. In an ultrasonic flowmeter with the transducers separated by a distance L=25mm, the line joining the transducers make an angle 60° with the direction of the flow. The transit time difference between upstream and downstream measurements is 10 ns with the sound velocity in the medium being 1000 m/s. Assuming that the size of the transducers is very small as compared to the diameter of the pipe, the flow velocity is

(A) 0.2m/s

(B) 2m/s

(C) 0.4m/s

(D) 40m/s

31. The seismic mass of an accelerometer oscillates sinusoidally at 100Hz with a maximum displacement of 10mm from its mean position. The peak acceleration of the seismic mass is

- (A) 3947.84m/s² (C) 314.15m/s²
- 3141.50m/s^2
- (D) 100.00m/s^2

A different push-pull type capacitive displacement sensor (nominal capacitance $C_0 = 0.01 \mu F$) is connected in two adjacent arms of an ac bridge in such a way that the output voltage of the bridge is independent of the frequency of the supply voltage. Supply to the bridge is 1V at 1kHz, and two equal resistance ($R = 3.9 k\Omega$) are placed in the other two arms of the bridge. The bridge sensitivity is

(A) 0.001 mV/pF

(B) 0.05mV/pF

(C) 0.1 mV/pF

(D) 0.5mV/pF

33. In a variable-area flow meter (Rota meter), the inlet tube diameter is the same as that of the effective float diameter and the tube is small. When the volume flow rate of a fluid is Q1, the float stands at a height of 70mm from the inlet and when the volume flow rate of the fluid is Q2, the float moves to a height of 20mm from the inlet. The ratio of the flow rates Q1/Q2 is

(A) 3.5

(B) 0.29

(C) 0.082

(D) 12.3

34. Which type of flow meter measures flow by measuring volume directly?

(A) Coriolis

(B) Magnetic

(C) Positive displacement

(D) Differential pressure

35. The third wire of a RTD (in three lead configuration) for temperature measurement by RTD is used

(A) to complete the bridge

(B) to compensate the errors due to lead resistance

(C) to balance the current flowing in the bridge

(D) to balance the null voltage of the bridge



- 36. The fluid flow through an orifice is
 - (A) directly proportional to the differential pressure across the orifice
 - (B) inversely proportional to the differential pressure across the orifice
 - (C) directly proportional to the square root of the differential pressure across the orifice
 - (D) None of the above
- 37. A transmitter installed in a hazardous area with associated safety barrier fails to work near 20mA. The probable cause of failure is
 - (A) transmitter calibration is out
 - (B) transmitter is non-linear
 - (C) transmitter needs zero elevation
 - (D) internal resistance of the safety barrier is too high
- 38. The Reynolds number determines
 - (A) Venturi effect
 - (B) the Coriolis acceleration
 - (C) the fluid viscosity
 - (D) whether the flow is laminar or turbulent
- 39. The sensitivity of Zirconia probe oxygen analayzer
 - (A) is increased at low concentration of oxygen
 - (B) is increased at high concentration of oxygen
 - (C) is increased at high temperature of probe
 - (D) remains same irrespective of oxygen concentrations

40. Dead band of an instrument is the band that prevents the instrument from being tampered with by unauthorized persons the range of values for which the instrument gives inaccurate readings the size of the instrument, indicated by the divisions on the scale of the instrument the range through which an input signal may be changed, on reversal of direction, without observable change in output Dead weight tester represents 41. (A) Laboratory standard (B) Ultimate standard (C) Transfer standard (D) None of the above To make an accurate measurement with a (an) the circuit 42. connections must be broken. (A) Oscilloscope (B) Voltmeter (C) Logic analyzer (D) Wattmeter 43. An analog and digital multimeter is basically a(an) and respectively. (A) Voltmeter and Ammeter (B) Ammeter and Voltmeter (C) Ammeter and Wattmeter (D) Voltmeter and Wattmeter 44. Which of the following cannot be used for AC measurement? (A) Moving iron instrument (B) Electrodynamometer type instruments (C) Permanent magnet moving coil instruments

(D) None of the above

load current measured by an ammeter with a resistance of 0.12Ω .


A 12V source supplies 25A to the load and would be the

61714

45.


	(A) 20 Amps (C) 24.9 Amps	(B) 12 Amps (D) 15 Amps	
46.	negligible resistance conr	Ω are connected in each arm of a Wheatstone by a 2V battery source. A galvanometer of nected to the bridge can sense as low a current ue of the resistance that can be measured is	C
	(A) 20mΩ (C) 20μΩ	(B) $2\mu\Omega$ (D) None of the above	
47.	What occurs if the ter junction is lower than the	mperature of the thermocouple measuring reference junction?	
	(C) The polarity stays	output ge polarity is reversed s the same, but voltage increases the same when temperature changes	
48.	In a rotameter, the pressure	e drop across the float	
	 (A) remains same thro (B) increases with inc (C) decreases with inc (D) None of the above 	crease in flow	
49.	A Hall probe of thickness in a magnetic field of 0.55 coefficient of the probe in	2×10^{-3} carrying a current of 0.2A is placed T and produces a voltage of 0.4V. The Hall terms of consistent unit is	
	(A) 1×10^{-3} (C) 0.5×10^{-3}	(B) 8×10^{-3} (D) 4×10^{-3}	*

- 50. Why is it important to maintain an impedance match from the source to the load when sending signals?
 - To reduce external noise (A)
 - (B) To keep the line balanced
 - (C) To reduce reflected energy
 - (D) To reduce attenuation
- 51. The figure shows the cross-sectional diagram of an orifice flow meter with an orifice radius R. Point 'a' is 30R upstream while points 'b' and 'c' are 0.8R and 30R downstream from the orifice respectively. The pressures at points a, b and c are Pa, Pb and Pc respectively. Then



- (A) $P_c > P_b > P_a$ (C) $P_a > P_b > P_c$
- (B) $P_b > P_c > P_a$ (D) $P_a > P_c > P_b$

- 52. Four strain gauges are fixed on a cylindrical shaft to measure torque, as shown in the figure.




A correct way to place these gauges in the bridge is

- (A) P-1, Q-2, R-3, S-4
- (B) P-1, Q-3, R-2, S-4
- (C) P-3, Q-1, R-2, S-4
- (D) P-2, Q-1, R-3, S-4

61714.

A thermocouple based temperature measurement system is shown in the figure. Relevant thermocouple emf data (in mV) is given below. The cold junction is kept at 0°C. The temperature is 30°C in the other parts of the system. The emf V₀ is measured to be 26.74mV. The temperature of the hot liquid is



Temperature	Emf of Chromel-	Emf of Copper-
Tomporature	Constantan	Constant
10°C	0.591	0.391
20°C	1.192	0.789
30°C	1.801	1.196
370°C	26.549	19.027
380°C	27.345	19.638

(A) 370.0°C

(B) 372.4°C

(C) 376.6°C

(D) 380.0°C

- 54. A strain gauge has a nominal resistance of 600Ω and a gauge factor of 2.5. The strain gauge is connected in a dc bridge with three other resistances of 600Ω each. The bridge is excited by a 4V battery. If the strain gauge is subjected to a strain of $100\mu\text{m/m}$, the magnitude of the bridge output will be
 - (A) 0V

2

(B) 250μV

(C) 500μV

(D) 750μV

A temperature sensitive transducer subjected to a sudden temperature change takes 10 seconds to reach the equilibrium condition. What will be the response time of the transducer to reach half of the temperature change?

(A) 3.46 sec

(B) 1.39 sec

(C) 6.93 sec

(D) cannot be determined

56. The speed of a gear having 60 teeth is measured using a proximity sensor. The output of the proximity sensor is fed to a counter with a gating time of 1s. The counter indicates a value of 120. The speed at which the gear is rotating is

(A) 60 rpm

(B) 120 rpm

(C) 600 rpm

(D) 1200 rpm

57. A Transducer is subjected to a sudden change in the measurand. It takes 10 seconds to reach the steady state condition. How long will it take to read half the measurand?

(A) 5sec

(B) 2.5sec

(C) 2.39sec

(D) 1.39sec

58. A thermometer with a time constant of 0.5 min is introduced in a bath where the temperature is increasing at a constant rate of 5°C/min. The steady state error in the thermometer reading is

(A) 10°C

(B) 2.5°C

(C) 0.1°C

(D) 0.4°C



59. Match the instruments on the left used for calibration of the instruments on the right,

-	Inverted Bell	5.	Low Pressure Gauge
	Dead Weight Tester		Gas Flow meter
	Knudsen Gauge	7.	Very low pressure measurement
4.	Mc Leod Gauge	8.	Pressure Gauges

- (A) 1-8, 2-5, 3-6, 4-7
- (B) 1-6, 2-8, 3-7, 4-5
- (C) 1-6, 2-5, 3-8, 4-7
- (D) 1-7, 2-8, 3-5, 4-6

60. A displacement sensor has an input range of 0 to 3 cm and a standard supply voltage $V_s=0.5V.$ Using the calibration results given in the table estimate maximum non-linearity as a % of fsd

D:1								
Displacement cm	0	0.5.	10	15	2.0	25	2.0	
Output voltage - 1	7 0		1.0	1.5	2.0	2.5	5.0	
Output voltage m\	/ 0	16.5	32.5	44.0	51 5	55 5	58.0	
					0 1.0	22.2	20.0	

(A) 25.95%

(B) 52.95%

(C) 35.25%

(D) 53.25%

61. The following table gives the variations of resistance with temperature for a RTD

Tananaratura OC							
Temperature °C	15	18	21	24	26.5	29.5	33
Resistance	106.06	167.14	108.22	109.3	110.38	111.46	112.75

Find the linear approximation equation of the above resistance-temperature curve for a temperature variation between 25° C and 33° C about the mean value of 24° C

- (A) $R_{\theta} = 109.3[1 + 0.0034(\theta 24)]$
- (B) $R_{\theta} = 100.3[1 + 0.0034(\theta 24)]$
- (C) $R_{\theta} = 109.3[1 + 0.0014(\theta 24)]$
- (D) $R_{\theta} = 100.3 [1 + 0.0014(\theta 24)]$

In a Wheatstone bridge, the values of resistances of various arms are $P=1000\Omega$, $Q=100\Omega$, $R=2005\Omega$ and $S=200\Omega$. The battery has an emf of 5V and negligible internal resistance. The galvanometer has a current sensitivity of $10\text{mm/}\mu\text{A}$ and internal resistance of 100Ω . Calculate the sensitivity of bridge in terms of deflection per unit change in resistance

(A) $2.34 \text{ mm/}\Omega$

(B) 55.4mm/Ω

(C) $5.54 \text{ mm/}\Omega$

(D) 23.4mm/ Ω

63. A copper-constantan thermocouple was found to have a linear calibration between 0°C and 400°C with emf at maximum temperature (reference junction temperature 0°C) equal to 20.68mV. If the indicated emf is 8.92mV in thermocouple circuit, determine the temperature of hot junction

(A) 197.53°C

(B) 179.53°C

(C) 157.53°C

(D) 193.53°C

64. Two currents from different sources flow in opposite directions through a resistor. I_1 is measured as 79mA on a 100mA analog instrument with an accuracy of \pm 3% of fsd. I_2 determined as 31mA, is measured on a digital instrument with an accuracy of \pm 100 μ A. Calculate the maximum and minimum levels of the current in resistor.

(A) 5.37 mA, 4.63mA

(B) 50.37mA, 45.63mA

(C) 50.37mA, 4.63mA

(D) 45.63mA, 5.37mA

65. The dead zone in a certain pyrometer is 0.125% of span. The calibration is 400°C to 1000°C. What temperature difference might occur before it is detected?

(A) 0.25°C

(B) 0.75°C

(C) 7.5° C

(D) 2.5°C

66. The resistance $R(\theta)$ of thermistor at temperature 0K is given by $R(\theta) = \alpha e^{\theta/\theta}$. Given that the resistance at the ice point is $9K\Omega$ and the resistance at the steam point is $0.5K\Omega$. Find the resistance at 25° C.

(A) 6.344 KΩ

(B) 4.366 KΩ

(C) 3.644 KΩ

(D) 5.334 KΩ

67. A pressure sensor has the following specifications: Sensitivity at the design temperature=10V/MPa, Zero drift = 0.01V/°C, Sensitivity drift = 0.01(V/MPa)/°C. When the sensor is used in an ambient 20°C above the design temperature, the output from the device is 7.4 V. The true value of the pressure will be

(A) 0.65 MPa

(B) 0.68 MPa

(C) 0.71 MPa

(D) 0.61MPa

68. A thermo couple system has a time constant of 10s. The system is used to measure the temperature of a furnace which fluctuates sinusoidally between 640°C and 600°C, with a periodic time of 80s. What are the maximum and minimum values of the temperature indicated?

(A) 640°C and 600°C

(B) 630°C and 610°C

(C) 635.7°C and 604.3°C

(D) 628.5°C and 608.5°C

69. A micro cantilever type micro accelerometer is designed by scaling down each dimension of the micro accelerometer by a factor of 100. If the natural frequency of the accelerometer is ω, then the natural frequency of the micro accelerometer will be

(A) 100 ω

(B) 10 ω

(C) 0.1ω

(D) 0.01 ω.

		1	8	
70.	condition	on. A 200kΩ fixed resi	OΩ and gauge factor 2.0 is at zero st stance is connected in parallel with esent an equivalent strain of	rain h it.
	(A)	+5290 μm/m	(B) zero	
		–123.8 μm/ m	(D) -300 μm/m	
71.	between at 100° nonline	n 0 and 300°C. With ref	ele is to be used to measure temperaterence junction at 0°C, the emf induses 15268 μV, E ₃₀₀ =16325 μV. Then entage of full scale is (B) -1.06%	iced
	(C)	-0.96%	(D) -3.23%	
72.			ascal is equivalent to	
	(A)	0.0689476, 6.80460×	10^{-2} and 7.03069×10^{2}	
	(B)	0.980665, 0.967841 an	id 10 ⁴	
	(C)	10^{-5} , 9.86923×10 ⁻⁶ and	1.01972×10 ⁻¹	
	(D)	133 322 1 31579×10	and 13 5951	

73. In a Venturimeter the flow is $0.15 \text{m}^3/\text{sec}$, when the differential pressure is 30kN/m². What will be the value of flow when the differential pressure is 60 kN/m²?

(A) $0.212 \text{ m}^3/\text{sec}$

(B) $0.106 \text{ m}^3/\text{sec}$

(C) $0.3 \text{ m}^3/\text{sec}$

(D) $0.075 \,\mathrm{m}^3/\mathrm{sec}$

74. A Piezo electric transducer has an output voltage of 3V at no load condition and has a capacitance of 250pF. It is connected to load capacitance of 125pF. The voltage across the load at high frequencies

(A) 1V

(B) 2V

(C) 9V

(D) Cannot be determined

(A) 10.0%

(B) 5.0%

(C) 2.5%

(D) 2.2%

76. For a steady flow of liquid, the float of the rotameter will remain in a particular position when

- (A) drag force is balanced by the weight of the float and buoyancy force
- (B) weight of the float is balanced by the drag force and buoyancy force
- (C) buoyancy force is balanced by the drag force and weight of the float
- (D) drag force and buoyancy together is slightly greater than the weight of the float

77. A 3½ - digit seven segment LED display uses diodes that requires a 20mA forward current. Calculate the total supply current required

(A) 4.6 mA

(B) 46mA

(C) 460mA

(D) 0.46 A

78. With the signal generator frequency of a Q meter set to 1.25MHz, the Q of a coil is measured as 98 when C=147pF. Determine the coil inductance and resistance.

(A) $L = 110 \mu H, R = 8.8 \Omega$

(B) $L = 11 \mu H, R = 8.8 \Omega$

(C) $L = 110 \mu H, R = 8.8 k\Omega$

(D) $L = 10 \text{mH}, R = 8.8 \text{k}\Omega$

79. An unknown circuit behaves as a $0.005\mu F$ capacitor in series with a $8k\Omega$ resistor when measured at a frequency of 1kHz. The terminal resistance is measured by an ohm meter as $134k\Omega$. Determine the components.

(A) $R = 8k\Omega$, $X = 31.8k\Omega$

(B) $R = 134k\Omega, X = 33.8k\Omega$

(C) $R = 8\Omega$, $X = 31.8k\Omega$

(D) $R = 8k\Omega, X = 131.8k\Omega$

¹80. Determine the displayed rise time when a pulse waveform with rise time of 21ns is applied to an oscilloscope that has an upper cut-off frequency of 50MHz.

(A) 22 ns

(B) 22 μs

(C) 220 ns

(D) 2.2 ms

81. A highly sensitive galvanometer can detect a current as low as 0.1nA. This galvanometer is used in a Wheatstone bridge as a detector. The resistance of galvanometer is negligible. Each arm of the bridge has a resistance of 1KΩ. The input voltage applied to the bridge is 20V. Calculate the smallest change in resistance which can be detected. The resistance of galvanometer can be neglected as compared to internal resistance of the bridge

(Α) 30μΩ

(B) 20μΩ

(C) 10μΩ

(D) 12.5μΩ

82. A certain resistor has a voltage drop of 110.2V and current of 5.3A. The uncertainties in the measurements are ±0.2V and ±0.06A respectively. What is the uncertainty in power?

(A) ±2.32%

(B) ±3.85%

(C) $\pm 1.15\%$

(D) ±5.84%

83. The bandwidth of a CRO is 20MHz. The fastest rise time a sine wave can be accurately reproduced by the instrument is

(A) 35 ns

(B) 12.8 ns

(C) 0.25 ns

(D) 17.5 ns

84. A velocity control system has a range of 220 to 460 mm/s. If the set point is 327mm/s and measured value is 294 mm/s, calculate the error as % of span.

(A) 17.35%

(B) 15.75%

(C) 11.35%

(D) 13.35%

d.c. resistance on account of

eddy current losses

(A) skin effect

The effective resistance of a coil at high frequencies is more than its

The inductance of a MI instrument is given by L= $(10+5\theta+\theta^2)\mu H$,

(B) proximity effect

(D) All of the above

85.

86.

	where θ is the deflection in radian from zero position. The spring constant is $12*10^{-6}$ Nm/rad. Estimate the deflection for a current of
	(A) 96.8° (C) 69.8° (B) 86.9° (D) 89.6°
87.	A Hay bridge operating at a supply frequency of 100Hz is balanced when components are C_3 =0.1 μ F, R_1 =1.26K Ω , R_3 =75 Ω and R_4 =500 Ω . Calculate the Q factor of the coil.
	(A) 112 (C) 108 (B) 212 (D) 231
88.	Power flowing in a three-phase, three-wire balanced load system is measured by two wattmeter method. The reading of wattmeter A is 7500W and of wattmeter B is -1500W. If the voltage of the circuit is 400V, what is the value of capacitance which must be introduced in each of the phase to cause the whole of power measured to appear on wattmeter A? The frequency is 50Hz.
	(A) 1060μF (C) 2106μF (B) 1060 pF (D) 2160PF
89.	A PMMC instrument with FSD of $100\mu A$ and $R_m=1K\Omega$ is to be employed as a voltmeter with FSD of $100V(rms)$. Silicon diodes are used in the rectifier circuit. Calculate the multiplier resistor value required.
	 (A) 980.7KΩ (B) 780.9KΩ (C) 890.7KΩ (D) 790.7KΩ

(C) 89.6°

	22
90.	What value of shunt resistance is required for using a $50\mu A$ meter movement with an internal resistance of 250Ω , for measuring $(0-500\text{mA})$?
	(A) 0.135Ω (B) 0.053Ω (C) 0.085Ω (D) 0.025Ω
91.	Calculate the tilt angle if in-phase 60Hz ac signals are applied to the deflection plates of a CRO, so that $E_V=38V$, $E_h=14V$ peak.
	(A) 69.8° (B) 96.8°

A 0.5 Volt RMS voltage is across a 50Ω resistor. Express this value in 92. dBV and dBm.

(D) 60.8°

(B) -6.02dBV, 6.97dBm (A) -6.02dBV, -6.97dBm (D) 6.02dBV, 6.97dBm (C) 6.02dBV, -6.97dBm

What is the voltage resolution of a digital oscilloscope with an 8-bit 93. ADC when the sensitivity is 200mV/div? (Assume the ADC range spread over 8 vertical divisions).

> (B) $6.3 \mu V$ (A) 6.3V (D) 0.063 mV (C) 6.3mV

A reciprocal counter that has a time base clock frequency of 100MHz 94. counts 5 time base periods during 20 cycles of the input signal. What is the frequency of the signal?

> (B) 40MHz (A) 4MHz (D) 40kHz (C) 60kHz

With the signal generator frequency of a Q meter set to 1.25MHz, the 95. Q of the coil is measured as 98 when C=147pF. Determine the coil inductance and resistance.

> (B) 110pF and $8.8k\Omega$ (A) $110\mu F$ and 8.8Ω (D) $10\mu F$ and 8Ω (C) 110F and 8.8MΩ

	23
96.	A pulse waveform with a $3.3k\Omega$ source resistance is to be displayed on an oscilloscope with an input capacitance of 15pF. The shortest pulse width that can be displayed without noticeable distortion being introduced by the combination of R and C will be
	(A) 109 μS (C) 10.9 mS (B) 1.09 μS (D) 1.09 nS
97.	Find the value of C required to compensate a 10:1 probe when the oscilloscope input capacitance is 30pF and the coaxial cable capacitance is 100pF.

(A) 1.30pF (B) 0.3pF (C) 130pF (D) 1300pF

98. A digital frequency meter has a time base derived from a 1MHz clock frequency divided by decade counters. Find the measured frequency when 1.512kHz sine wave is applied and the time base uses four decade counters.

> (A) 15kHz (B) 1.5 kHz (C) 150 kHz (D) 0.15 kHz

99. A PMMC instrument has FSD of $100\mu A$ and coil resistance of $1k\Omega$. Calculate the required shunt resistance value to convert the instrument into an ammeter with FSD=1A.

> (A) $10001 \text{ k}\Omega$ (B) 0.10001Ω (C) $0.0001 \text{ k}\Omega$ (D) $100 \text{ k}\Omega$

A simple emitter follower voltmeter circuit has $V_{CC}=20V$, $R_s + R_m = 9.3 k\Omega$, $I_m = 1 mA$ at full scale and transistor $h_{FE} = 100$. Calculate the voltmeter input resistance.

> (A) $1 M\Omega$ (B) $1k\Omega$ (C) 0.1Ω (D) $10.9k\Omega$

101.	Find th	e signal freque the signal from	ency at which m 600Ω source	a pro	be with Z _i =10M S	2. 3.5pF
	(A) (C)	7.58kHz 75.8MHz	S 14 he i	(B) (D)	7.58Hz 75.8kHz	
102.	Find the 21ns is of 20M	applied to an	se time when a oscilloscope t	a pulse that ha	waveform with ris an upper cut off	se time of frequency
	(A) (C)	27ns 27μs		(B) (D)	37ms 37s	
103.	A diffe	n mode gain o	fier has a di of 0.05. The c	fferenc ommo	e mode gain of n mode rejection r	1000 and atio of the
	(A) (C)	5000 15000		(B) (D)	20000 10000	
104.		eviations are s			5Ω are connected ne resultant resistar	
	(A) (C)	250Ω±20Ω 250Ω±15.89	Ω	(B) (D)		
105.	For sign	nal conditionir	ng of a Piezo e	lectric-	type transducer, w	e require
	(A) (B) (C) (D)					
106.	transdu		ed to a consta	ant acc	sensitivity of 100r celeration of 5g. T	
	(A) (C)	0V 0.5V		(B) (D)	100mV 5V	

- 107. An accelerometer has a seismic mass of 100μg and natural frequency of 1KHz. With 'g' the acceleration due to gravity, the static sensitivity of the accelerometer in nm/g is
 - (A) 2.58nm/g
- (B) 9.81nm/g
- (C) $7.28 \times 10^2 \text{nm/g}$
- (D) $6.28 \times \text{nm/g}$
- 108. A Pirani gauge measures vacuum pressure and works on the principle of
 - (A) change in ionizing potential
 - (B) change in thermal conductivity
 - (C) deformation of elastic body
 - (D) change in self-inductance
- 109. Match the following:

P.	Radiation pyrometer	W.	Angular velocity measurement
Q.	Dall tube	X.	Vacuum pressure measurement
R.	Pirani gauge	Y.	Flow measurement
S.	Gyroscope	Z.	Temperature measurement

- (A) P-Z, Q-W, R-X, S-Y
- (B) P-Z, Q-Y, R-X, S-W
- (C) P-W, Q-X, R-Y, S-Z
- (D) P-Z, Q-X, R-W, S-Y
- 110. The output voltage of a transducer with an output resistance of $10 \text{K}\Omega$ is connected to an amplifier. The minimum input resistance of the amplifier so that the error in recording the transducer output does not exceed 2% is
 - (A) $10K\Omega$

(B) 49KΩ

(C) 490KΩ

(D) $1.2M\Omega$

111. Match the essential amplifier characteristics with the sensing applications given below:

	Amplifier Characteristics		Sensing Applications
P.	Charge amplifier with very low bias current and high input impedance	L.	Strain gauge in unipolar DC Wheatstone bridge
Q.	Voltage amplifier with low bias current and very high input impedance	M.	Glass electrode pH sensor
R.	Voltage amplifier with very high CMRR	N.	Piezo electric sensor for measurement of static force

- (A) P-L, Q-M, R-N
- (B) P-M, Q-N, R-L
- (C) P-N, Q-L, R-M
- (D) P-N, Q-M, R-L
- 112. Vena contracta is the cross-section where the flow area is a minimum for a restriction-type flow meter. For an orifice meter, if d is the diameter of the orifice opening, then the area of the vena contracta is approximately
 - (A) $\pi d^2/4$

(B) $0.99 \, \pi d^2/4$

(C) $0.8 \, \pi d^2/4$

- (D) $0.6 \, \pi d^2/4$
- 113. Different types of transducers and signal conditioning circuits are given below.

Match the transducer with the appropriate signal conditioning circuit commonly used with it.

P.	Thermocouple	11	DC bridge
Q.	Strain gauge	2.	Phase sensitive detector
R.	Piezo electric sensor	3.	Charge amplifier
S.	LVDT	4.	Cold junction compensation
		5.	Instrumentation amplifier

- (A) P-2, Q-3, R-5, S-1
- (B) P-1, Q-5, R-2, S-3
- (C) P-4, Q-1, R-2, S-5
- (D) P-4, Q-1, R-3, S-2

Which of the following flow meter has the lowest pressure drop for a

Venturi meter

(D) Rotameter

114.

given range of flow?

(A) Orifice meter

(C) Flow nozzle

115.	Two copper-constantan thermocouples are connected such that the two constantan wires are joined together. The two copper wires are connected to the input of a low noise chopper stabilized differential amplifier having a gain of 1000. One of the thermocouple junctions is immersed in a flask containing ice and water in equal proportion. The other thermocouple is at a temperature T. If the output of the amplifier is 2.050V, the temperature T is	
	(A) 205°C (C) 51.25°C (B) 102.5°C (D) 50°C	
116.	Poisson's ratio for a metal is 0.35. Neglecting Piezo resistive effect, the gauge factor of a strain gauge of this metal is	
	(A) 0.65 (C) 1.35 (B) 1 (D) 1.70	
117.	The values of the material constant β for thermistors P and Q are 4000K and 3000K, respectively. The resistance of each thermistor at 298K is $2K\Omega$. At 373K, the ratio of the resistance of thermistor P to that of thermistor Q will be closest to	
	(A) 1.33 (C) 0.75 (B) 1.00 (D) 0.50	
118.	The temperature being sensed by a negative temperature coefficient (NTC) type thermistors is linearly increasing. Its resistance will	
	 (A) linearly increase with temperature (B) exponentially increase with temperature (C) linearly decrease with temperature (D) exponentially decrease with temperature 	

119.	junction	nocouple is made n is kept at a ten the ambient ten	mperature of	100°C	and the referen	ice junction	ı is
		700μV 3010μV			1000μV 5300μV		
120.	device	ne constant of is used to mean ag at about 5°C/	sure temperat	ture o	f the air in a		
		static uncertain	1171	, ,	dynamic None of the a	bove	
121.	You no couple	m, you press of tice that the tac of seconds abo order meas	on the throttle chometer over out 3000rpm	and or shoots until i	change the rpm 3000rpm and	oscillate fo	om or a
		first order second order			zero order cannot be dete	ermined	
122.	subject this ele	element made ed to a magnet ement is 2mm at, what is the vo	ic flux densit. When a cu	y of 0	.75Wb/m ² . Th	e thickness	5 0
		45V 4.5mV		(B) (D)	4.5V 0.45V		
123.	What index =	is the light =1.5.	velocity wi	thin t	he glass? Gl	ass refrac	tiv
	(A) (C)	2×10 ⁸ m/s 20 ×10 ⁸ m/s	d Chic.	(B) (D)	0.2×10 ⁸ m/s 2×10 ⁸ km/s		

124.	What is acceptance angle of a fiber when n ₁ (core refractive index) = 1.48 and n ₂ (cladding refractive index) = 1.46?						
		38.07° 14.07°		(B) (D)	28.07° 18.07°		
125.	attenuat				stance for a fiber link with inched is 1mW and receiver		
	(A) (C)			(B) (D)	14km 34km		
126.	core dia				ded index optical fiber if its are is 0.275 and its operating		
	(A) (C)	431 143		(B) (D)	341 134		
127.	_			_	uantum efficiency is 1% and ard current of 50mA?		
	, ,	0.345mW 537mW		(B) (D)	0.735mW 7.35mW		
128.	saturati		_		35A/W and the input-power current if the incident light		
	(A) (C)	0.85mA 8.5mA		(B) (D)	85mA 75mA		
129.	For a bandwi		τ_{TR} and τ_{I}	RC ar	e 100ps each. What is its		
	(A) (C)	156GBit/s 789GBit/s		(B) (D)			

How much will a light pulse spread after traveling along 5km of step index fiber whose NA is 0.275 and $n_1 = 1.487$?

(A) 84.76 ns/km

(B) 74.76 ns/km

(C) 84.76 ms/km

(D) 74.76 ms/km

131. A Piezo electric transducer has a capacitance of 100pF and a charge sensitivity of 4×10⁻⁶ Coulomb/cm. The connecting cable has capacitance of 400pF. The display device has an input impedance of 1MΩ resistance and 50pF capacitance connected in parallel. What is the voltage sensitivity of Piezo electric transducer alone?

(A) 4000Volts/cm

(B) 40 Volts/cm

(C) 40mVolts/cm

(D) 400Volts/cm

A longitudinal Piezo resistor is embedded on the top of a silicon cantilever near the anchored base. The cantilever points in the (110) direction. The Piezo resistor is p-type doped with resistivity of 7.8Ω-cm. Find the longitudinal gauge factor of the Piezo resistor. Young's Modulus of silicon crystal is 168GPa

(A) 320

(B) 120.6

(C) 220.6

(D) 215.6

133. A fixed-free cantilever is made of single crystal silicon. The longitudinal axis of the cantilever points in the [100] crystal orientation. The resistor is made by diffusion doping with longitudinal gauge factor of 50. The length, width, and thickness of the cantilever are 200μm, 20μm and 5μm respectively. If a force 100μN is applied at the end of the cantilever in the longitudinal direction, what is the magnitude of stress?

(A) 1MPa

(B) 2MPa

(C) 1.7MPa

(D) 2.9 MPa

- 134. A body is dropped from a height of 10m and suffers a shock when it hits the ground. If the duration of the shock is 5ms, calculate the magnitude of the shock in terms of "g"?
 - (A) 312g

(B) 286g

(C) 686g

- (D) 231g
- 135. Dummy strain gauges are used for
 - (A) calibration of strain gauges
 - (B) increasing the sensitivity of the bridge
 - (C) compensating for differential expansion
 - (D) compensating for temperature changes
- 136. Strain gauge rosettes are used
 - (A) when the direction of principal stress is known
 - (B) when the direction of principal stress is not known
 - (C) when the direction of hoop stress is not known
 - (D) when the direction of hoop stress is known
- 137. Two strain gauges are used to measure strain in a cantilever, one above and one below. The two strain gauges are connected in the adjacent arms of a Wheatstone bridge, the bridge configuration is called
 - (A) quarter bridge

(B) half bridge

(C) full bridge

- (D) null bridge
- 138. The loading effect of a potentiometer is due to
 - (A) the output meter resistance
 - (B) potentiometer resistance
 - (C) both (A) and (B)
 - (D) the construction

¹ 139.	The re	solution of a potentiometer to	ansdu	cer can be increased by
				and the microaded by
	(A)	0		
	(B)	O Potentionic	ter	
*	(C)	using helipots		
	(D)	All the above		
140.	The ch	ange in resistivity due to stra	in in s	train gauges is known as
	(A)	Piezo-electric effect	(B)	Piezo-resistive effect
	(C)		(D)	
	(-)	and sometime client	(1)	Hall effect
141.	The gai	uge factor of a metallic strain	gauge	e is given as
	(A)	1+2v	(D)	AD/D / AT /T
	(C)		(B)	$\Delta R/R / \Delta L/L$
	(0)	ANL	(D)	Both (A) and (A)
142.	The ma	terial with highest gauge fac	tor is	
	(A)	Nickel	(7)	
				Manganin
	(C)	Platinum	(D)	Doped silicon
143.	The ma	terial with almost zero tempe	erature	co-efficient of resistance is
	(A)	Nichrome	(D)	Incolortio
		Constantan		Isoelastic
	(0)	Constantan	(D)	Manganin
144.	A recict	ance wire studie		
	gtool at	ance wife strain gauge with	a gau	ge factor of 2 is bonded to a
	Steel St	ructure subjected to a stres	s of 1	00MN/m ² . The modulus of
	elasticit	y of steel is 200GN/m ² . The	perce	entage change in the value of
	the gaug	ge resistance due to the appli	ed stre	ss is
	(A)	0.01%	(B)	0.1%
	(C)	10%	(D)	None of the above
				Trong of the above
145.	A the	rmistor is used for measuring	7	
	(A)	temperature	(B)	flow
	(C)	pressure		
	(0)	product	(D)	All of the above

146.	The LV displace	VDT is used to measure	the d	lirection and magnitude	of
· ·	(A) (B) (C) (D)	by using a phase sensitive no by using an AC Voltmeter by using a DC Voltmeter None of the above	nodula	itor	
147.	The c	apacitive transducer cannot b	e use	d for	
	(A) (C)	static input Both (A) and (B)	(B) (D)	dynamic input quasi state	
148.	Abso	lute encoders are generally li	mited	to measurement of	
	(A) (C)	quarter revolution lay revolution	(B) (D)	single revolution multiple revolution	
149.	While s	selecting a transducer for a pa	rticul	ar application	
	(A) (B) (C) (D)	only the input characteristic only the output characteristic only the transfer characteristic input, output and transfer ch	ics sho tics sh	ould be considered nould be considered	red
150.	A Hall	Effect transducer can be used	d for th	he measurement of	
	(A) (C)	power displacement	(B) (D)	current All of the above	
